

To: Enphase Solar Installers

Subject: IQ Combiner 4 missing rivets for Enphase Mobile Connect mounting

SKUs Affected:

- X-IQ-AM1-240-4

Affected installations: Installing an Enphase Mobile Connect with IQ Combiner 4

If you intend to add an Enphase Mobile Connect to the IQ Combiner 4, a pair of rivets are required for the installation, as the IQ Combiner 4 currently does not ship with rivets for mounting the cell modem (CELLMODEM-M1). The new Enphase Mobile Connect SKUs (CELLMODEM-M1-06-AT-05 and CELLMODEM-M1-06-SP-05) **do** ship with a pair of rivets that can be used for the installation. However, the older SKU (CELLMODEM-M1) does not include rivets. Thus, when installing a CELLMODEM-M1 on a IQ Combiner 4 (X-IQ-AM1-240-4), please procure a pair of rivets from Enphase Support or your local hardware store for the installation.

Required Actions for Installers: Reach out to Enphase Support to order the rivets

If you plan to install a CELLMODEM-M1 on site with the IQ Combiner 4(X-IQ-AM1-240-4), please reach out to Enphase Support. The team will ship you a pair of rivets that can be used for completing the installation. Alternately, you can procure a pair of rivets from a local hardware store. The rivets used should meet the following specifications:



Dimension	Value(inches)
A	0.315
B	0.071
C	0.35
D	0.158
E	0.43
F	0.256-0.295
G	4.1-4.2

Upcoming Changes to Affected SKUs

All new IQ Combiner 4's (X-IQ-AM1-240-4) will include 2 rivets that can be used for installing the older Enphase Mobile Connect (CELLMODEM-M1).